

Sheet 1 of 2

THIS FORM REPLACES DR FORM 40, JAN 02  
PREVIOUS EDITIONS WILL BE DESTROYED

**THE FOLLOWING INFORMATION IS REQUIRED FOR ALL ACCIDENTS**

INDICATE BY DIAGRAM WHAT HAPPENED


AGENCY CASE NO.  
B5-084584



Indicate  
North  
by Arrow



**POI approximate**  
**16' west of the east curb of 13th**  
**18' north of the south curb of E st**



**Not To Scale**

**DESCRIPTION OF ACCIDENT BASED ON OFFICER'S INVESTIGATION**

Driver 1 stated he was stopped on E street at 13th waiting for traffic to clear so he could proceed west on Est. Driver 1 stated he thought it was safe to cross through the intersection, however as he started through the intersection he did not see vehicle 2 approaching and they collided in the intersection. Driver 2 stated she was traveling northbound on 13th, approaching the intersection of E street in the inside traffic lane at an estimated speed of 35 MPH. She stated vehicle 1 suddenly pulled out, onto 13th from Est. Driver 2 said she steered to the left to avoid the collision, but was unsuccessful and vehicle 1 struck her car on the right front. No injuries were reported at the scene. The intersection of 13th and Est is controlled by stop signs on Est indicating all traffic on Est must stop and yield to all traffic on 13th

<b>PROPERTY</b>	OBJECT DAMAGED	OWNER NAME	ADDRESS	PHONE	APPROX. COST OF DAMAGE \$
	OBJECT DAMAGED	OWNER NAME	ADDRESS	PHONE	APPROX. COST OF DAMAGE \$
<b>WITNESSES</b>	NAME ADDRESS PHONE				
	NAME ADDRESS PHONE				

VEHICLE MOVEMENT BEFORE COLLISION				POINT OF IMPACT AND MOST DAMAGED AREA <i>(Enter numbers for each vehicle)</i>				AIRBAG DEPLOYED VEHICLE 1		RESTRAINT USE VEHICLE 1		TOTAL OCCUPANTS			
VEH NO.	N	S	E	W	VEHICLE 1		VEHICLE 2								
1			X		E street										
2	X				13th street										
1	01				POINT OF IMPACT	08	POINT OF IMPACT	02	1 Deployed - front		1 None used - vehicle occupant		Driver No. 1		
2	01				MOST DAMAGED AREA	08	MOST DAMAGED AREA	02	2 Deployed - side		2 Lap & shoulder belt used		Driver No. 2		
				06 Turning left				3 Deployed - both front/side		3 Shoulder belt only used		Pedestrian			
				07 Making U-turn				4 Not deployed		4 Lap belt only used					
				08 Entering traffic lane				5 Not applicable/ No airbag available		5 Child safety seat used					
				09 Leaving traffic lane				6 Unknown		6 Child booster seat used					
				10 Parked						7 DOT approved helmet used					
				11 Slowing or stopped in traffic						8 Costume helmet used					
				12 Other						9 Restraint use unknown					
				13 Unknown											
				01 Essentially straight ahead											
				02 Backing											
				03 Changing lanes											
				04 Overtaking/ Passing											
				05 Turning right											

OFFICER NO. <b>941</b>	TROOP/ TEAM/ BEAT <b>4</b>	DEPARTMENT <b>Lincoln Police Department</b>	Photographs taken? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
INVESTIGATOR NAME (Print or Type) <b>Michael Pratt</b>		INVESTIGATOR SIGNATURE <b>Approved by Officer Michael Pratt</b>	
DATE OF REPORT <b>09/14/2015</b>			